

Radon Testing Results - Harney ESD Service Center

Action Level is 4.0 pCi/L

| Site Name | Building Name | Room Description (per floor plan) | Kit serial # | Date Sampled | Type of test | Results (pCi/L) |
|---------------------------|---------------|--------------------------------------|--------------|--------------|--------------|--------------------|
| Harney ESD Service Center | ESD Building | Computer Room A | 9545423 | 12/07/20 | Detector Kit | 4.0 |
| Harney ESD Service Center | ESD Building | Computer Room D | 9545619 | 12/07/20 | Duplicate | 3.9 |
| Harney ESD Service Center | ESD Building | Conference Room 2 | 9545412 | 12/07/20 | Detector Kit | 1.1 |
| Harney ESD Service Center | ESD Building | Conference Room 3 | 9545637 | 12/07/20 | Detector Kit | 0.8 |
| Harney ESD Service Center | ESD Building | Kitchen A | 9545625 | 12/07/20 | Detector Kit | 0.9 |
| Harney ESD Service Center | ESD Building | Kitchen D | 9545632 | 12/07/20 | Duplicate | 1.4 |
| Harney ESD Service Center | ESD Building | Large Conference Room A | 9545647 | 12/07/20 | Detector Kit | 1.1 |
| Harney ESD Service Center | ESD Building | Large Conference Room D | 9545646 | 12/07/20 | Duplicate | 1.0 |
| Harney ESD Service Center | ESD Building | Library | 9545413 | 12/07/20 | Detector Kit | 1.3 |
| Harney ESD Service Center | ESD Building | Lobby | 9545422 | 12/07/20 | Detector Kit | 1.2 |
| Harney ESD Service Center | ESD Building | Lobby Office | 9545421 | 12/07/20 | Detector Kit | 1.4 |
| Harney ESD Service Center | ESD Building | Office 1 | 9545430 | 12/07/20 | Detector Kit | 1.2 |
| Harney ESD Service Center | ESD Building | Office 1b | 9545414 | 12/07/20 | Blank | < 0.3 |
| Harney ESD Service Center | ESD Building | Office 2 | 9545602 | 12/07/20 | Detector Kit | 1.2 |
| Harney ESD Service Center | ESD Building | Office 25-1 A | 9545408 | 12/07/20 | Detector Kit | 1.3 |
| Harney ESD Service Center | ESD Building | Office 25-1 B | 9545406 | 12/07/20 | Blank | < 0.3 |
| Harney ESD Service Center | ESD Building | Office 25-2 | 9545620 | 12/07/20 | Detector Kit | 1.8 |
| Harney ESD Service Center | ESD Building | Office 25-3 | 9545411 | 12/07/20 | Detector Kit | 1.4 |
| Harney ESD Service Center | ESD Building | Office 3 | 9545639 | 12/07/20 | Detector Kit | 0.7 |
| Harney ESD Service Center | ESD Building | Office 4 | 9545605 | 12/07/20 | Detector Kit | 1.3 |
| Harney ESD Service Center | ESD Building | Office A | 9545429 | 12/07/20 | Detector Kit | 3.7 |
| Harney ESD Service Center | ESD Building | Office B | 9545407 | 12/07/20 | Detector Kit | 3.9 |
| Harney ESD Service Center | ESD Building | Office C | 9545627 | 12/07/20 | Detector Kit | 3.5 |
| Harney ESD Service Center | | | 9537802 | | Spike | 29.8 |

ACTION REQUIRED

- The EPA's recommended action level for radon is 4 pCi/L and will require mitigation by the district, followed by retesting.
- [1 number] of spike tests were conducted to ensure the integrity of the testing process and all spike tests passed satisfactorily.