Fixture Location/Description	Fixture ID #	Test Date	Test Resu
Kitchen Faucet	20180100-001KF	1/6/2021	1.04
Main Drinking Fountain	20180100-002DW	1/6/2021	5.2
Classroom Sink 1	20180100-003CF	1/6/2021	4.83
Classroom Sink 2	20180100-004CF	1/6/2021	7.77
Girls Bathroom Left Sink	20180100-005BF	3/23/2021	2.74
Girls Bathroom Right Sink	20180100-006BF	3/23/2021	12.7
Boys Bathroom Left Sink	20180100-007BF	3/23/2021	13.1
Boys Bathroom Right Sink	20180100-008BF	3/23/2021	13.7
anitor Sink	20180100-009SF	10/29/2021	1.44
Teacherage 1			
/acant/Water is shut off			
Nill test prior to occupancy if/when building is return	ned to useage and water is turne	а раск оп.	
Feacherage 2			
(itchen Sink	20180103-001KF	3/23/2021	1.88
Master Bath Sink	20180103-002BF	3/23/2021	12.4
Guest Bath Sink	20180103-003BF	3/23/2021	3.34
aundry Room	20180103-004BF	3/23/2021	8.48
Gym Restrooms			
Girls Bathroom Left Sink	20180105-001BF	3/23/2021	12
Sirls Bathroom Right Sink	20180105-002BF	3/23/2021	8.02
Boys Bathroom Left Sink	20180105-003BF	3/23/2021	6.8
Boys Bathroom Right Sink	20180105-004BF	3/23/2021	9.67

ND = Non Detect - Lead level is below the set detection limits

of 1 ppb